

BRACKENRIDGE PARK CULTURAL LANDSCAPE REPORT SAN ANTONIO, TEXAS

Prepared for
Brackenridge Park Conservancy
San Antonio Parks & Recreation and
San Antonio River Authority



Reed Hilderbrand, LLC
Doug Reed
John Grove
Christina Sohn

Suzanne Turner Associates
Suzanne Turner
John Welch
Herpreet Singh
Ashley Braquet

January 2020

In Collaboration with
The Lady Bird Johnson Wildflower Center
Michelle Bertelsen

BRACKENRIDGE PARK CULTURAL LANDSCAPE REPORT SAN ANTONIO, TEXAS

Prepared for
Brackenridge Park Conservancy
San Antonio Parks & Recreation Department and
San Antonio River Authority
January 2020



BRACKENRIDGE PARK
CONSERVANCY



CITY OF SAN ANTONIO
PARKS & RECREATION



SAN ANTONIO
RIVER AUTHORITY

Brackenridge Park
3700 N. St. Mary's Street
San Antonio, TX 78212
www.brackenridgepark.org

Cover Image: Circa 1970s, children playing in the Tuleta Street Low-Water Crossing, with families picnicking and seated on rockwalls.

Photo Credit: *San Antonio-Express News*

Reed Hilderbrand, LLC
Doug Reed
John Grove
Christina Sohn

Suzanne Turner Associates
Suzanne Turner
John Welch
Herpreet Singh
Ashley Braquet

In Collaboration with
The Lady Bird Johnson Wildflower Center
Michelle Bertelsen



TABLE OF CONTENTS

LIST OF FIGURES	VI
FOREWORD	XIV
ACKNOWLEDGEMENTS	XVI
PREFACE	XVIII
EXECUTIVE SUMMARY	XXIV
INTRODUCTION PART 1	3
The Brackenridge Park Landscape	3
INTRODUCTION PART 2	23
Brackenridge Park CLR Overview and Outcomes	23
PART ONE: CONTEXTS	47
Introduction to Contexts	49
Chapter 1. River Cities	53
Chapter 2. New Directions in Preservation	63
Chapter 3. Park Development and Design in the United States	85
Chapter 4. American Tourism and Automobiles in Parks	107
Chapter 5. Ethnographic Imprints on the Landscape	117
Chapter 6. The Ecology of Brackenridge Park	139
Chapter 7. George Brackenridge, a Portrait	149
PART TWO: PAST	163
Introduction to Site History	165
Chapter 8. Living with Water, Prehistory–1690	169
Chapter 9. Managing the Water, 1691–1844	183
Chapter 10. Urban and Industrial Evolution, 1845–1898	195
Chapter 11. San Antonio’s Municipal Park, 1899–1949	213
Chapter 12. Brackenridge Park Enters the Modern Era, 1950–Present	255

PART THREE: PRESENT	287
Introduction to the Present	289
Chapter 13. Existing Conditions	293
Chapter 14. Analysis and Evaluation	385
PART FOUR: FUTURE	427
Introduction to Treatment	429
Chapter 15. Treatment Plan	433
GLOSSARY OF TERMS AND ACRONYMS	485
BRACKENRIDGE PARK GRAPHIC TIMELINE	495
BRACKENRIDGE PARK TIMELINE	501
BRACKENRIDGE PARK ECOLOGICAL SITE ASSESSMENT	559
BIBLIOGRAPHY	633

LIST OF FIGURES

Figure –1. View of a historic carriage way in Brackenridge Park	4
Figure –2. View of people canoeing and picnicking in Brackenridge Park	4
Figure –3. View of erosion along the banks of the San Antonio River	6
Figure –4. An 1871 plan of Central Park by Olmsted and Vaux.	10
Figure –5. A circa 1929 blueprint of Brackenridge Park shows its organic form	11
Figure –6. A 1730 –1800s map of the San Antonio acequia system, created circa 1970s	12
Figure –7. Engraving of Indigenous people building the acequia at Mission San José	12
Figure –8. The White Shaman Rock Art Panel	13
Figure –9. Photo of a piñata is seen hanging from a tree in Brackenridge Park.	15
Figure –10. Photo of a man barbecuing ribs during the Easter celebration	15
Figure –11. An 1894 plan of Boston’s Emerald Necklace by Olmsted, Olmsted & Eliot.	18
Figure –12. A map shows the potential National Heritage Area along the San Antonio River	21
Figure –13. A map shows the geographic context of Brackenridge Park within South Texas	25
Figure –14. Major drainages associated with Brackenridge Park	27
Figure –15. A Brackenridge Park Project Boundary map shows limits of the CLR study.	28
Figure 1–1. The 240-mile-long San Antonio River	54
Figure 1–2. View of the Mississippi River and concrete levee walls	55
Figure 1–3. View of the Cheonggyecheon Stream after removal of the elevated highway.	56
Figure 1–4. Two diagrams illustrate the 1890s transformation from long, narrow agricultural plots.	58
Figure 1–5. Photo of downtown San Antonio after the flood of September 1921	59
Figure 1–6. A dotted line shows the location of the cutoff channel	59
Figure 1–7. A promotional plan of the San Antonio River Walk, proposed in 1929.	61
Figure 1–8. Photo of Inlet Tunnel flood control structure at Josephine Street.	62
Figure 2–1. Pictured is the San Antonio River Walk in the first decade of the 2000s.	65
Figure 2–2. Photo of the Alamo, circa 1900s	66
Figure 2–3. An original plan of the pueblo of San Fernando.	67
Figure 2–4. A photo of houses that once stood on Laredo Street.	67
Figure 2–5. Contemporary map of the system of Spanish missions	68
Figure 2–6. 1857 painting entitled “Crockett Street Looking West,” by German-born painter	69
Figure 2–7. Headquarters of the San Antonio Conservation Society	70
Figure 2–8. Navarro Street after 1921 flood.	71
Figure 2–9. Illustration of San Antonio’s acequia and mission system by 1778	74

Figure 2–10. A map shows the San Antonio missions property included in the UNESCO.	75
Figure 2–11. A 2013 excavation of the original Alamo dam.	76
Figure 3–1. View of the mall in Central Park, circa 1902	86
Figure 3–2. An early plan of Central Park. The title reads, “A picturesque guide	87
Figure 3–3. A view of the Blenheim Palace landscape in the English countryside.	88
Figure 3–4. Two photos of the Red Book for Vinters, Kent, 1797	88
Figure 3–5. Two photos of Downing’s 1841 Treatise.	89
Figure 3–6. A contemporary aerial view of the 1847 Birkenhead Park	90
Figure 3–7. View of Birkenhead Park with boathouse	90
Figure 3–8. A contemporary aerial view of Central Park	93
Figure 3–9. The circuit of roadways in Olmsted and Vaux’s plan for Central Park.	93
Figure 3–10. Ansel Adams’ “El Capitan,” Yosemite.	95
Figure 3–11. 1933 Master Plan for Yellowstone National Park.	96
Figure 3–12. Aerial perspective of the World’s Columbian Exposition.	98
Figure 3–13. In 1914, Houston industrialist George Hermann deeded Houston 285 acres.	99
Figure 3–14. A 1932 photo of the main entrance to Houston’s Hermann Park	99
Figure 3–15. A photo of the Vulcan colossal sculpture in Vulcan Park.	101
Figure 3–16. The Dreyfous Bridge is an art deco bridge in New Orleans City Park.	101
Figure 3–17. Pictured is the 1985 draft plan for rescuing New York’s Central Park from neglect.	104
Figure 3–18. The ability of park planners to respond organically to changes over time	104
Figure 4–1. A painting by William Guy Wall entitled “Cauterskill Falls on the Catskill Mountains.	108
Figure 4–2. A January 1917 article discusses San Antonio’s ability to compete with California	109
Figure 4–3. A sketch shows the park and boulevard system George Brackenridge envisioned	111
Figure 4–4. Postcard of the Wawona Big Tree tunnel in Yosemite, circa 1917-1920	112
Figure 4–5. Postcard of “A Yellowstone Public Automobile Camp,” circa 1920.	114
Figure 4–6. Detail of the 1921 “Ward Map of the City of San Antonio”	115
Figure 4–7. Circa 1917 photo shows a horse-drawn carriage and an automobile	115
Figure 5–1. “Eye of God” painting on the ceiling of the Mission Concepcion library room	118
Figure 5–2. Circa 1870–1880 quilt made by Antonia Ruiz Herrera.	119
Figure 5–3. Photo of two tortilleras making tortillas in San Antonio in 1944.	120
Figure 5–4. Map illustrating the route of original Canary Islanders to San Antonio via Vera Cruz	121
Figure 5–5. Some African Americans worked in the cattle industry	124
Figure 5–6. Circa 1850 Map of Plaza de las Islas, laid out in the 1700s by Canary Island settlers	125
Figure 5–7. Map illustrating German settlement in the Texas Hill Country between 1850–1865	128
Figure 5–8. Two circa 1857 half-timbered houses in Kendall County, northwest of Bexar County	130
Figure 5–9. The lower pump house in Brackenridge Park, constructed in 1885	131

Figure 5–10. A map illustrating San Antonio’s racial composition	133
Figure 5–11. An enlargement of the 2013 “Racial Dot Map”	133
Figure 5–12. Photo of a family celebrating Easter in Brackenridge Park	136
Figure 5–13. A traditional Coahuiltecan dance being performed at a San Antonio mission.	136
Figure 6–1. Four images illustrate varied landscape experiences in Brackenridge Park	140
Figure 6–2. A diagram shows Brackenridge Park’s three primary soil types	144
Figure 6–3. A diagram shows Brackenridge Park’s ecological health.	145
Figure 6–4. Top: diagram shows existing conditions of stormwater runoff.	147
Figure 7–1. Portrait of George Brackenridge at age 79, 1911	150
Figure 7–2. Portrait of the Brackenridge family, circa late 1880s	151
Figure 7–3. San Antonio’s First National Bank Building.	153
Figure 7–4. Portrait of George and Eleanor Brackenridge taken in 1920	155
Figure 7–5. Brackenridge’s Victorian mansion in San Antonio.	156
Figure 7–6. A photo of George Brackenridge aboard his and his brothers’ houseboat.	157
Figure 7–7. Rincon/Riverside/Frederick Douglass School at 701 North St. Mary’s Street	158
Figure 7–8. Bronze sculpture of George Brackenridge	159
Figure 8–1. The White Shaman Rock Art Panel in the Lower Pecos Canyonlands	170
Figure 8–2. Detail of a geologic landform map of southwest Texas shows	172
Figure 8–3. Alpine Drive pedestrian trail in the northwest portion of Brackenridge Park	173
Figure 8–4. A painting representing two semi-nomadic groups of the San Antonio area.	175
Figure 8–5. Detail of the White Shaman Mural, interpreted as showing elements of water	179
Figure 9–1. A painting representing the 1691 meeting between Cabeza de Vaca	184
Figure 9–2. Engraving of Indigenous people building the acequia.	186
Figure 9–3. Illustration of the Spanish and secular acequias of San Antonio	187
Figure 9–4. This survey compares the 1836 boundaries of the Alamo site with the 1890 map	191
Figure 9–5. Circa 1860 oil painting entitled “Lavanderas (Wash Day on San Pedro Creek)”.	192
Figure 10–1. Stereograph of San Pedro Springs, circa 1869, taken by Ernst Wilhelm Raba	196
Figure 10–2. San Pedro Springs, circa 1877. The character of the park is evident.	196
Figure 10–3. Engraving of the Old Sweet Homestead	198
Figure 10–4. 1865-1868 map of Confederate tannery and surrounding features.	200
Figure 10–5. Circa 1890 photo of a family using an acequia for laundering	202
Figure 10–6. Circa 1940-1950s photograph of Pump House No. 1	203
Figure 10–7. 1886 Bird’s Eye View of San Antonio	204
Figure 10–8. The Portland Alamo Cement smokestack, circa 1920s.	208

Figure 10–9. 1883 advertisement in The San Antonio Light, listing properties for sale	209
Figure 10–10. Circa 1947 photo of the large Victorian mansion George Brackenridge constructed	210
Figure 10–11. Circa 1880s, a trio of visitors standing on a makeshift crossing of the river	211
Figure 11–1. This 1905 map shows the layout of both Brackenridge Park and Mahncke Park.	214
Figure 11–2. This carriage way in Brackenridge Park demonstrates organic circulation.	215
Figure 11–3. 1921 “Ward Map of San Antonio Including Suburbs Both North and South.”	217
Figure 11–4. Image of a streetcar on River Avenue (today Broadway), near Brackenridge Park.	218
Figure 11–5. A small group of Elk browse and forage in one of the open areas of the park	219
Figure 11–6. “River Ave. Home” facing Brackenridge Park for sale, October 9, 1906.	220
Figure 11–7. The Adams=Kirkpatrick Company advertised lots for sale in Laurel Heights, 1907.	221
Figure 11–8. R. H. Russell & Co. advertises a suburban residence	221
Figure 11–9. A photo shows the linear pool area at San Pedro Springs.	222
Figure 11–10. Bison, large numbers of elk, and a carriage way or bridle path	223
Figure 11–11. A photo captures part of the system of wells and pumps that was drilled in 1891.	225
Figure 11–12. Post card illustrating the use of the quarry walls	227
Figure 11–13. Works Progress Administration plaque located at Koehler Pavilion	228
Figure 11–14. A. W. Tillinghast, noted early golf course designer, inspects the scene at Brackenridge Park.	229
Figure 11–15. Undated map of the Brackenridge Park Municipal Golf Links after their completion.	230
Figure 11–16. Bathers at Lambert Beach.	231
Figure 11–17. Local man becomes the “donkey man” at Brackenridge Park.	232
Figure 11–18. Children ride the Merry-Go-Round at Lions Field.	233
Figure 11–19. An undated photo of the Lions Club Fieldhouse at Brackenridge Park.	233
Figure 11–20. An automobile drives through the low-water crossing at Tuleta Drive. J.	234
Figure 11–21. Visitors traverse various elevated stone walkways in the sunken garden.	235
Figure 11–22. Announcement of the installation of the Japanese Tea Garden at Golden Gate Bridge	236
Figure 11–23. View of the Japanese Tea Garden.	237
Figure 11–24. Photo of the Jingu family members standing on a faux bois bridge	237
Figure 11–25. In the far right side of the postcard, you can see the original stage	238
Figure 11–26. This photograph shows the condition of buildings in the “Mexican Village.”	238
Figure 11–27. Polo players compete at the polo field at Brackenridge.	240
Figure 11–28. Miraflores arch of Spanish Talavera mosaic tile.	241
Figure 11–29. American Institute of Architects members attending a national convention in 1931	241
Figure 11–30. The St. Mary Street Bridge in 1921 during the flood that fall.	242
Figure 11–31. Workers reassemble the “Letters of Gold” bridge	242
Figure 11–32. An early photograph of the Witte Museum prior to the 1961 expansion	245
Figure 11–33. The Rodriguez Wooden Footbridge has 33 pairs of vertical tree trunks	246
Figure 11–34. Lover’s Lane walkway connected the Japanese Tea Garden and the zoo.	247
Figure 11–35. Madarasz Bridge between the back of the Witte and the Ilka Nursery site.	248

Figure 11–36. J. Ray Lambert was Superintendent of the San Antonio Parks Department.	248
Figure 11–37. The Sunken Garden Theater was expanded and improved.	250
Figure 11–38. April 10, 1950 San Antonio Light article noting the Easter celebration.	251
Figure 11–39. The Starter House at Brackenridge Park	252
Figure 11–40. Undated photo of the Low-Water Crossing at Avenue A	253
Figure 12–1. The Brackenridge Park Eagle, Dec. 01, 1959.	256
Figure 12–2. This image shows overhead portions of the HemisFair skyride	257
Figure 12–3. Juneteenth celebrations occurred in several places in San Antonio and at Seguin.	259
Figure 12–4. Photo of a member of the Cerna family	260
Figure 12–5. A view of McAllister Freeway.	262
Figure 12–6. A comparison of Brackenridge Park’s vehicular drives	263
Figure 12–7. Overlay map showing San Antonio’s historic acequia system	266
Figure 12–8. A panoramic view of Tunnel Inlet Park	267
Figure 12–9. Period Plan: 1899 – 1914.	271
Figure 12–10. Period Plan: 1915 – 1929.	273
Figure 12–11. Period Plan: 1967 – present.	275
Figure 12–12. Period Plan Comparison of Programmed Space.	277
Figure 12–13. Period Plan Comparison of Park Boundaries.	279
Figure 12–14. Period Plan Comparison of Circulation.	281
Figure 12–15. Period Plan Comparison of Buildings.	283
Figure 12–16. Period Plan Comparison of Programmed Space.	285
Figure 13–1. Birds-eye view of Brackenridge Park in relation to Downtown San Antonio.	295
Figure 13–2. Regional Watershed Context Map.	295
Figure 13–3. Brackenridge Park Adjacencies.	297
Figure 13–4. Diagram of existing views and vistas.	299
Figure 13–5. Diagram of existing topography and landforms.	301
Figure 13–6. Brackenridge Park’s Landscape Systems.	304
Figure 13–7. Character Zones Map.	305
Figure 13–8. View of erosion along banks of the San Antonio River, August 2019.	306
Figure 13–9. Diagram of existing hydrology form.	308
Figure 13–10. Diagram of existing flood zones.	309
Figure 13–11. View of river walls, southwest of bathhouse, February 2019.	311
Figure 13–12. View of river walls, south of zoo, February 2019.	311
Figure 13–13. Diagram of existing river edges.	312
Figure 13–14. Diagram of existing hydrology management.	313
Figure 13–15. Enlargement from 13–14 of existing hydrology management.	315

Figure 13–16. Diagram of existing canopy	318
Figure 13–17. Diagram of existing ground plane vegetation	319
Figure 13–18. Diagram of existing varied character of vegetation	320
Figure 13–19. Diagram of existing ecological health.	321
Figure 13–20. View of Tuleta Drive entrance, February 2019	324
Figure 13–21. Diagram of existing vehicular drives.	326
Figure 13–22. Composite diagram of existing circulation features.	327
Figure 13–23. Diagram of existing pedestrian paths	329
Figure 13–24. Diagram of existing parking in park	330
Figure 13–25. View of zoo edge adjacent to Upper Labor acequia, August 2019	332
Figure 13–26. View of zoo edge adjacent to bathhouse, February 2019.	332
Figure 13–27. Diagram of existing internal edges in the park.	333
Figure 13–28. View of stone architecture and lower pumphouse # 2	335
Figure 13–29. Map of existing structures throughout the park.	337
Figure 13–30. Diagram of existing development and spatial organization	339
Figure 13–31. Diagram of designated picnicking areas	340
Figure 13–32. Diagram of existing park programming and uses	341
Figure 13–33. Overall Site Plan.	345
Figure 13–34. Cultural Core Enlargement	347
Figure 13–35. Zoo Edge Enlargement	349
Figure 13–36. Sunken Garden Theater and Japanese Tea Garden Enlargement	351
Figure 13–37. Site Plan: South End Park Enlargement	353
Figure 13–38. View into Miraflores from the bank of the San Antonio River.	355
Figure 13–39. View of the historic irrigation channel	356
Figure 13–40. View of an exposed portion of the Upper Labor Dam as it exists today	357
Figure 13–41. View of Arched Iron Truss Bridge	360
Figure 13–42. View of historic WPA Picnic Grounds under tree canopy	361
Figure 13–43. View of the Lambert Beach Softball Field	362
Figure 13–44. View of back of Witte Museum, looking across the San Antonio River	363
Figure 13–45. View of the Japanese Tea Garden as it exists today	367
Figure 13–46. View of Sunken Garden Theater from Alpine Drive.	367
Figure 13–47. View of Mexican Village structures and cement company smokestack	367
Figure 13–48. Transitional zone on North St. Mary’s Street.	369
Figure 13–49. View of sports field north of the driving range and the First Tee site.	370
Figure 13–50. View of low-water crossing on Tuleta Drive	372
Figure 13–51. View of old carriage way converted to a jogging/walking path	373
Figure 13–52. View of Catalpa-Pershing drainage ditch	374
Figure 13–53. View of Davis Park.	376

Figure 13–54. View of southern riparian corridor south of the golf course	377
Figure 13–55. View of southern riparian corridor west of the golf course	378
Figure 13–56. Drone footage view of Lions Field	379
Figure 13–57. View of Tunnel Inlet Park.	380
Figure 13–58. A walkway in the San Antonio Zoo	381
Figure 13–59. Brackenridge Park Golf Course, February 2019	382
Figure 14–1. Brackenridge Park’s Landscape Systems	389
Figure 14–2. Character Zones Map	395
Figure 15–1. Brackenridge Park Landscape Systems	441
Figure 15–2. Interpretation Precedents-1.	453
Figure 15–3. Interpretation Precedents-2.	455
Figure 15–4. Brackenridge Overall Site Plan	461
Figure 15–5. Brackenridge Treatment Approaches	484
Figure 15–6. Brackenridge Project Recommendations.	485
Figure 17–1. Timeline: Context.	497
Figure 17–2. Timeline: Preservation & Archaeology-1.	498
Figure 17–3. Timeline: Preservation & Archaeology-2.	499
Figure 17–4. Timeline: Cultural and Ethnic Imprints and Population Shifts-1.	500
Figure 17–5. Timeline: Cultural and Ethnic Imprints and Population Shifts-2	501

